

TELEMETER



A **Telemeter** may be necessary to measure the volume of the room for disinfection or insect removal. It gives precise measurements with a laser beam to evaluate lengths accurately. The area and volume function is used to calculate the dimensions of a room.

Max. measuring range: 20 m

DIMENSIONS



REFERENCE

	REFERENCE
TELEMETER	3010.601